



Underwriters Laboratories Inc.®

Northbrook, IL Santa Clara, CA
Melville, NY Research Triangle Park, NC

An independent, not-for-profit organization testing for public safety

LAN WIRING COMPLIANCE CERTIFICATE

Certificate Number: 157358102002

Issue Date: 10/04/02

Issued to: **Jyh Eng Industrial Co., Ltd.**
6 Fl. 11 Lane 1, Sec. 1 Yeong An S. Rd.
Lu-Chou Shiang
Taipei Hsien, Taiwan

Report Reference:

E157358, 10/3/02

The following:

Permanent Link/Channel Identification:

Link-1, -2, -3, -4, -5, -6, -7, -8, -9, -10, -11, -12, -13, -14, -15;
Channel-1, -2, -3, -4, -5, -6, -7, -8, -9, -10, -11, -12, -13, -14, -15

Category Designation:

Category 6

Located At: Jyh Eng Industrial Co., Ltd.
6 Fl. 11 Lane 1, Sec. 1 Yeong An S. Rd.
Lu-Chou Shiang
Taipei Hsien, Taiwan

Have been investigated by Underwriters Laboratories Inc. on Oct. 3, 2002, and found to be in compliance with the ANSI/TIA/EIA-568-B.2-1, June 20, 2002 Edition. The test data generated during this investigation was developed using the Model WireScope 350.

The issuance of this Certificate in no way implies Listing, Classification, or Recognition by UL and does not authorize the use of the UL Listing, Classification, or Recognition Marks or any other reference to UL on or in connection with the product or system. The test data generated for the purposes of this investigation only apply to the Link(s) or Channel(s) stated above. The tests do not guarantee future compliance of the subject Link(s) or Channel(s). In no event shall UL be responsible to anyone for whatever use or non-use is made of the information contained in this Certificate and in no event shall UL, its employees, or its agents, incur any obligation or liability for damages, including, but not limited to, consequential damages arising out of or in connection with the use, or inability to use, the information contained in this Certificate.

Test Engineer:

Review Engineer: